2018

		TOTAL	PRIOR	18/19	19/20	20/21	21/22	22/23	PE	RW	CON
SHOPP - Bridge Preservation											
Bridge - State (HBRR)		\$61,415	\$10,401	\$10,666	\$24,923	\$15,425			\$16,002	\$3,516	\$41,897
National Hwy System		\$22,120	\$4,405		\$17,715				\$4,188	\$772	\$17,160
	TOTAL	\$83,535	\$14,806	\$10,666	\$42,638	\$15,425			\$20,190	\$4,288	\$59,057
SHOPP - Collision Reduction											
National Hwy System		\$25,079	\$4,324	\$16,875	\$1,168	\$2,712			\$5,919	\$191	\$18,969
Surface Transportation Program	1	\$32,670	\$2,476	\$9,847	\$20,347				\$6,847	\$2,852	\$22,971
	TOTAL	\$57,749	\$6,800	\$26,722	\$21,515	\$2,712			\$12,766	\$3,043	\$41,940
SHOPP - Mandates											
National Hwy System		\$6,656	\$685	\$4,561			\$1,410		\$1,683	\$1,460	\$3,513
	TOTAL	\$6,656	\$685	\$4,561			\$1,410		\$1,683	\$1,460	\$3,513
SHOPP - Mobility											
National Hwy System		\$144,194	\$7,838	\$32,076	\$17,858	\$28,998	\$57,424		\$25,233	\$9,980	\$108,981
	TOTAL	\$144,194	\$7,838	\$32,076	\$17,858	\$28,998	\$57,424		\$25,233	\$9,980	\$108,981
SHOPP - Roadway Preservation											
National Hwy System		\$62,218	\$3,497	\$6,985	\$40,908	\$4,370	\$6,458		\$9,363	\$1,341	\$51,514
	TOTAL	\$62,218	\$3,497	\$6,985	\$40,908	\$4,370	\$6,458		\$9,363	\$1,341	\$51,514
	MPO TOTAL	\$354,352	\$33,626	\$81,010	\$122,919	\$51,505	\$65,292		\$69,235	\$20,112	\$265,005

MPO_ID	CTIPS ID	со	Dist	EA	Route	DESCRIPTION	PE	RW	CON		
SHOPP - Bridg	SHOPP - Bridge Preservation										
	11200000409	SJ	10	1F760	12	Near Terminous, at Little Potato Slough Bridge No. 29-0101. Replace joint seals and bearing pads using temporary pile supports.	1,458	927	4,260		
	11200000414	SJ	10	1F170	26	Near Stockton, at Route 26/99 Separation No. 29-0142 (PM 1.11). Establish standard vertical clearance.	2,425	20	9,333		
	11200000397	SJ	10	1C860	4	In Stockton, at Crosstown Freeway Viaduct No. 29-0269. Reconstruct hinge 32 (left and right) and three ramp joint seals.	1,496	152	4,059		
	11200000381	SJ	10	1C800	4	Near Discovery Bay, at Old River Bridge No. 29-0045. Upgrade mechanical and electrical equipment on movable bridge.	1,848	2,055	5,398		
	11200000418	SJ	10	1H342	5	In and near Lathrop, at Deuel Overhead No. 29-0262R/L. Improve to standard truck capacity.	1,423	510	9,400		
	11200000407	SJ	10	1C940	5	In Stockton, at the Stockton Channel Viaduct No. 29-0176L/R. Bridge deck rehabilitation at spot locations.	1,365	15	6,716		
	11200000384	SJ	10	0P540	5	In San Joaquin County, on Routes 5 and 580 and in Stanislaus County on Route 99, at various locations. Seismic retrofit of four bridges.	2,507	336	10,541		
	11200000380	SJ	10	0X310	99	In Stockton, at Route 4/99 Separation (Farmington Road) Bridge No. 29-0155. Replace structure to provide standard vertical clearance.	2,765	262	7,760		
	11200000398	SJ	10	1C880	99	Near Stockton, at Wilson Way Overcrossing No. 29-0118C. Remove existing damaged girder and build new overhang and barrier, resulting in reduced bridge	734	11	1,590		
	11200000425	SJ	10	0X460	5	width and increased vertical clearance. In Stockton, at the Stockton Channel Viaduct Bridge No. 29-0176L/R. Bridge rehabilitation to address structural and load carrying capacity deficiencies. (Long Lead Project)	4,169	0	0		
						SHOPP - Bridge Preservation Total:	20,190	4,288	59,057		

MPO_ID	CTIPS ID	со	Dist	EA	Route	DESCRIPTION	PE	RW	CON
SHOPP - Col	lision Reduction								
	11200000389	SJ	10	0X710	120	In and near Manteca, from east of McKinley Avenue to Route 99. Highway worker safety improvements.	1,132	20	4,299
	11200000391	SJ	10	0X700	205	In and near Tracy, from Hansen Road to Paradise Road. Highway worker safety improvements.	1,102	43	4,588
	11200000405	SJ	10	1E590	205	In San Joaquin, Stanislaus, and Tuolumne Counties, on Routes 4, 5, 99, 120, and 205 at various locations. Improve wet roadway surface conditions at twelve	930	31	4,697
	11200000403	SJ	10	1F460	4	locations. Near Holt, from 0.3 mile west to 0.5 mile east of Middle River Bridge. Realign curve, widen shoulders, upgrade guard rail, and install flashing beacons.	2,534	1,632	9,341
	11200000379	SJ	10	0X690	4	In Stockton, from Garfield Avenue to Route 99 at various locations. Highway worker safety improvements.	1,390	70	4,120
	11200000383	SJ	10	0X720	5	In and near Lathrop and Stockton, from south of Louise Avenue to Charter Way; also from south of Hammer Lane to north of Eight Mile Road (PM 32.3/35.7).	670	20	3,250
	11200000415	SJ	10	1C970	5	Highway worker safety improvements. In San Joaquin and Stanislaus Counties, on Route 5 at various locations; also in Merced County, on Route 152 at various locations. Install new or upgrade existing	1,549	14	2,233
	11200000396	SJ	10	1E531	88	safety devices to shield objects from errant vehicles. Near Clements, at Liberty Road. Improve intersection.	1,834	1,175	6,700
	10500000164	SJ	10	1C760	99	In and near Stockton and Lodi, at various locations from French Camp Road to Kettleman Lane; also at the Route 4 (PM R15.7 to R16.6) and Route 5 (PM 25.8 to 26.6) Interchange. Pave areas behind the gore, slopes, and at narrow locations,	1,625	38	2,712
						SHOPP - Collision Reduction Total:	12,766	3,043	41,940

2018

 MPO_ID	CTIPS ID	со	Dist	EA	Route	DESCRIPTION	PE	RW	CON		
SHOPP - Mandates											
	11200000417	SJ	10	1G510	12	In Lodi, from Stockton Street to Route 99. Upgrade pedestrian facilities to make compliant with the Americans with Disabilities Act (ADA) Standards.	1,056	1,394	1,410		
	11200000387	SJ	10	1C060	99	In Ripon, at Main Street Overcrossing; also in Lodi at Turner Road Overcrossing (PM 31.6). Upgrade pedestrian facilities to comply with Americans with Disabilities Act (ADA) requirements.	627	66	2,103		
						SHOPP - Mandates Total:	1,683	1,460	3,513		

MPO_ID	CTIPS ID	со	Dist	EA	Route	DESCRIPTION	PE	RW	CON
SHOPP - Mob	ility								
	11200000411	SJ	10	1C960	120	In and near Manteca and Lathrop, from Route 5 to Route 99; also on Route 5 at PM R13.34 and on Route 99 at PM 4.56. Install Intelligent Transportation System (ITS) field elements.	1,594	73	4,671
	11200000412	SJ	10	1G990	120	in San Joaquin, Amador, Calaveras, Merced, Mariposa, Stanislaus, and Tuolumne Counties, on Routes 4, 5, 26, 33, 49, 59, 88, 99, 104, 108, 120, 132, 140, 152 and	1,823	140	3,308
	11200000390	SJ	10	1C330	205	205 at various locations. Repair or replace damaged and nonfunctioning Traffic In Tracy, from Byron Road Undercrossing to Paradise Road Overcrossing. Install ramp meters and other Intelligent Transportation System (ITS) elements.	3,569	5,809	16,088
	11200000419	SJ	10	0H560	26	Near Linden, from 0.3 mile east of Fine Road to 0.1 mile west of Podesta Lane. Widen travel lanes and shoulders to improve the existing conditions for Surface	425	770	1,930
	11200000413	SJ	10	1F180	4	Transportation Assistance Act (STAA) trucks. In Stockton, from Route 5 to Route 99. Install ramp meters, traffic monitoring systems, Closed Circuit Television (CCTV), and synchronize intersection signals	7,990	1,936	46,579
	11200000410	SJ	10	1F400	5	with ramp metering. In and near Stockton, on Routes 4 (PM 14.6/21.2), 5 and 99 (PM 15.8/18.5) at various locations. Install Intelligent Transportation System (ITS) elements.	3,370	460	10,765
	11200000385	SJ	10	1C620	5	In various counties, on various routes, at various locations. Upgrade Transportation Management System (TMS) elements.	1,214	153	4,159
	11200000388	SJ	10	1C280	99	In Lodi, from south of Route 12 (Victor Road) to south of Turner Road. Realign northbound onramp, increase bridge vertical clearance and construct auxiliary lane.	2,327	167	13,309
	11200000406	SJ	10	1G750	99	In San Joaquin, Merced, and Stanislaus Counties, on Routes 5, 12, 59, 99, and 152 at various locations. Upgrade or replace inefficient and damaged Traffic Monitoring Station (TMS) elements.	2,921	472	8,172
						SHOPP - Mobility Total:	25,233	9,980	108,981

MPO_ID	CTIPS ID	со	Dist	EA	Route	DESCRIPTION	PE	RW	CON			
SHOPP - Roadway Preservation												
	11200000408	SJ	10	1C500	4	In Stockton, from 0.1 mile east of Fresno Avenue to west of Center Street. Roadway rehabilitation.	2,862	67	35,165			
	11200000382	SJ	10	1C200	5	In San Joaquin County, on Routes 4, 5, and 99 at various locations. Rehabilitate culverts.	1,595	270	3,775			
	11200000386	SJ	10	1C530	5	In San Joaquin County, on Routes 5 and 99, and in Stanislaus County, on Routes 5, at various locations. Upgrade sign panels and replace overhead sign	1,242	60	2,081			
	11200000401	SJ	10	0S740	88	structures. Near Lockeford, from 0.1 mile south of East Jack Tone Road to north of North Tully Road intersection; also near Kirkwood, in Alpine County (PM 0.3/2.4). Replace culverts.	1,695	625	4,035			
	11200000416	SJ	10	1E610	99	In and near Stockton and Lodi, at various locations from Eastside Underpass to Acampo Road; also on Route 4 at the Route 4/5 Separation (PM R16.10) and on Route 120 in Lathrop at Mossdale Underpass (PM R0.5). Upgrade drainage	1,969	319	6,458			
						SHOPP - Roadway Preservation Total:	9,363	1,341	51,514			